



Mechanical Properties

We know that ceramics are more brittle than metals. Why?

- Consider method of deformation

slippage along slip planes


in ionic solids this slippage is very difficult

too much energy needed to move one anion past another anion


1




Ceramic Fracture




Impact or point loading
(a)



Bending
(b)



Torsion
(c)



Internal pressure
(d)

2

Ceramic Fracture

Mirror region the first region of a brittle fracture surface, which is very smooth. Associated with slow but accelerating crack growth.



Mist region the second region of a brittle fracture surface; cloudy look caused by the crack propagating at up to the maximum velocity, but insufficient energy is being released to cause branching.

Hackle region the third region of a brittle fracture surface, rough and ridged. The crack branches while growing at maximum velocity, often resulting in a piece of material being ejected.

3


Ceramic Fracture

4



Glass Properties: Viscosity

- **Viscosity, η :**
relates shear stress and velocity gradient:



$$\tau = \eta \frac{dv}{dy}$$

η has units of (Pas)

7

Glass Compositions

Glass Type	Composition (wt%)						Characteristics and Applications
	SiO ₂	Na ₂ O	CaO	Al ₂ O ₃	B ₂ O ₃	Other	
Fused silica	>99.5						High melting temperature, very low coefficient of expansion (thermally shock resistant)
96% Silica (Vycor™)	96				4		Thermally shock and chemically resistant—laboratory ware
Borosilicate (Pyrex™)	81	3.5		2.5	13		Thermally shock and chemically resistant—ovenware
Container (soda-lime)	74	16	5	1		4MgO	Low melting temperature, easily worked, also durable
Fiberglass	55		16	15	10	4MgO	Easily drawn into fibers—glass-resin composites
Optical flint	54	1				37PbO, 8K ₂ O	High density and high index of refraction—optical lenses
Glass-ceramic (Pyroceram™)	43.5	14		30	5.5	6.5TiO ₂ , 0.5As ₂ O ₃	Easily fabricated; strong; resists thermal shock—ovenware


8



Glass Viscosity vs. T and Impurities

- **sodalime glass: 70% SiO₂ balance Na₂O (soda) & CaO (lime)**
 - **borosilicate (Pyrex): 13% B₂O₃, 3.5% Na₂O, 2.5% Al₂O₃**
 - **Vycor: 96% SiO₂, 4% B₂O₃**
 - **fused silica: > 99.5 wt% SiO₂**
-
- Viscosity decreases with T
 - Strain Point: fracture before deformation
 - Annealing Point: atomic diffusion fast enough to release strain in ~ 15 min.
 - Softening Point: Impurities lower T_{deform}
 - Working Point: limit of easy deformation

9




9


Heat Treating Glass

- Annealing:**
Removes internal stress caused by uneven cooling.
- Tempering:**
Puts surface of glass part into compression.
This suppresses growth of cracks from surface scratches.


before cooling



surface cooling




further cooled




compression
tension
compression



Result: surface crack growth is suppressed.



11



12



Ceramic Fabrication Methods II

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- Milling and screening: desired particle size
- Mixing particles & water: produces a "slip"
- Form a "green" component
- Dry and fire the component

15

Ceramic Fabrication Methods II

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

Hydroplastic forming:
extrude the slip (e.g., into a pipe)

Slip casting:

pour slip into mold absorb water into mold

"green ceramic"

solid component

pour slip into mold drain mold

"green ceramic"

hollow component

16

Clay Composition

A mixture of components used

- (50%) 1. Clay
- (25%) 2. Filler – e.g. quartz (finely ground)
- (25%) 3. Fluxing agent (Feldspar)
 - binds it together

aluminosilicates + K^+ , Na^+ , Ca^+

17

Features of a Slip


- **Clay** is inexpensive
- Adding water to clay
 - allows material to shear easily
 - along weak van der Waals bonds
 - enables extrusion
 - enables slip casting

Structure of Kaolinite Clay:


18

Drying


- Drying:** layer size and spacing decrease.



wet slip



partially dry



"green" ceramic


Drying too fast causes sample to warp or crack due to nonuniform shrinkage. Surface tension forces tight packing. Aerogel vs. Xerogel.

19

Firing

- Firing:**
 T raised to (900 to 1400°C).
vitrification: liquid glass forms from clay and flows between SiO_2 particles.
 Flux melts at lower T .

micrograph of
porcelain



SiO_2 particle
(quartz)

glass formed
around
the particle

20

Ceramic Fabrication Methods II


GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

Sintering: useful for both clay and nonclay compositions.

- Procedure:
 - produce ceramic and/or glass particles by grinding
 - place particles in mold
 - press at elevated T to reduce pore size.
- Aluminum oxide powder:
 - sintered at 1700°C
 - for 6 minutes.



Adapted from Fig. 13.17, *Callister 7e*.
(Fig. 13.17 is from W.D. Kingery, H.K. Bowen, and D.R. Uhlmann, *Introduction to Ceramics*, 2nd ed., John Wiley and Sons, Inc., 1976, p. 483.)

21

Powder Pressing


Sintering powder touches forms neck & gradually neck thickens

- add processing aids to help form neck
- little or no plastic deformation

Uniaxial compression compacted in single direction

Isostatic (hydrostatic) compression pressure applied by fluid powder in rubber envelope

Hot pressing pressure + heat



Adapted from Fig. 13.16, *Callister 7e*.

22

Tape Casting

- thin sheets of green ceramic cast as flexible tape (<2 mm)
- used for integrated circuits and capacitors
- cast from liquid slip (ceramic + organic solvent)

Adapted from Fig. 13.18, Callister 7e.

23

Ceramic Fabrication Methods III

<p>GLASS FORMING</p>	<p>PARTICULATE FORMING</p>	<p style="background-color: #00FF00; color: white; padding: 2px;">CEMENTATION</p>
<p><u>Clinker</u> :</p>	<p>Partially dehydrated mineral that forms cement or plaster with water</p>	
<p><u>Concrete</u> :</p>	<p>Aggregate of cement, sand, rock, air, water</p> <p>Good <u>Compressive</u> Strength .</p> <p>Medium <u>tensile</u> Strength (against stretching)</p>	
<p><u>Reinforced Concrete</u> :</p>	<p>Metal rods internal to add to Tensile strength</p> <p>1906, Unitarian Church, Oak Park, IL Frank Lloyd Wright</p>	

24

Ceramic Fabrication Methods III

GLASS
FORMING

PARTICULATE
FORMING

CEMENTATION

- Produced in extremely large quantities.
- Portland cement:
 - mix clay and lime bearing materials
 - calcinate (heat to 1400°C)
 - primary constituents:
 - tricalcium silicate
 - dicalcium silicate
- Adding water
 - produces a paste which hardens
 - hardening occurs due to hydration
- Forming: done usually minutes after hydration begins.

25

Early Cement

Etruscans

CaCO_3 (limestone) $\xrightarrow{\text{fire}}$ CaO (lime, quicklime)

$\text{CaO} + \text{H}_2\text{O} \longrightarrow \text{Ca(OH)}_2$ (slaked lime, paste, form to choice)

$\text{Ca(OH)}_2 + \text{CO}_2$ (air) \longrightarrow ~~Ca(OH)₂~~ $\text{Ca(CO}_3\text{)}$ + H_2O
 slow reformation of limestone in new form

Plaster: "Paris" - Gypsum based ($\text{CaSO}_4 \cdot x \text{H}_2\text{O}$) - 1790s




Cement: "Portland" - Alite and belite based - 1824
Thames Tunnel

$(\text{CaO})_x (\text{SiO}_2)$

$\text{Ca}_3 (\text{SiO}_4)_{1.5}$ most important

26


Early Cement

Clinker	Partial Hydration	Final Microstructure
		
$3\text{CaO} \cdot \text{Al}_2\text{O}_3 \cdot \text{CaSO}_4 \cdot 12\text{H}_2\text{O}$ <p style="text-align: center;">↑</p>		<p>Needles:</p> $3\text{CaO} \cdot \text{Al}_2\text{O}_3 \cdot 3\text{CaSO}_4$ <p style="text-align: center;">• 32 H₂O</p> <p style="text-align: center;">↑</p>

Early Cement

Several of the components present in modern cement powder are also found in the natural clinker *larinite*, which is *beta*-dicalcium silicate. As can be seen in this optical photomicrograph of a thin section, weathering effects at the surface of the mineral produce a primitive form of concrete.

Ca_2SiO_4




28



Application: Refractories

- Need a material to use in high temperature furnaces.
- Consider the Silica (SiO_2) - Alumina (Al_2O_3) system.
- Phase diagram shows:
mullite, alumina, and cristobalite as candidate refractories.



Adapted from Fig. 12.27, Callister 7e. (Fig. 12.27 is adapted from F.J. Klug and R.H. Doremus, "Alumina Silica Phase Diagram in the Mullite Region", *J. American Ceramic Society* **70**(10), p. 758, 1987.)

29



Application: Refractories


Refractory Type	Composition (wt%)							Apparent Porosity (%)
	Al_2O_3	SiO_2	MgO	Cr_2O_3	Fe_2O_3	CaO	TiO_2	
Fireclay	25-45	70-50	0-1		0-1	0-1	1-2	10-25
High-alumina fireclay	90-50	10-45	0-1		0-1	0-1	1-4	18-25
Silica	0.2	96.3	0.6			2.2		25
Periclase	1.0	3.0	90.0	0.3	3.0	2.5		22
Periclase-chrome ore	9.0	5.0	73.0	8.2	2.0	2.2		21

Source: From W. D. Kingery, H. K. Bowen, and D. R. Uhlmann, *Introduction to Ceramics*, 2nd edition. Copyright © 1976 by John Wiley & Sons, New York. Reprinted by permission of John Wiley & Sons, Inc.


30

Application: Die Blanks

- Die blanks:**
 Need wear resistant properties!




Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.



Adapted from Fig. 11.8 (d), Callister 7e.

- Die surface:**
 4 μm polycrystalline diamond particles that are sintered onto a cemented tungsten carbide substrate.
 polycrystalline diamond helps control fracture and gives uniform hardness in all directions.




Courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.


31

Application: Cutting Tools


- Tools:**
 for grinding glass, tungsten, carbide, ceramics
 for cutting Si wafers
 for oil drilling
- Solutions:**
 manufactured single crystal or polycrystalline diamonds in a metal or resin matrix.
 optional coatings (e.g., Ti to help diamonds bond to a Co matrix via alloying)
 polycrystalline diamonds sharpen by microfracturing along crystalline planes.




oil drill bits



blades



coated single crystal diamonds




polycrystalline diamonds in a resin matrix.

Photos courtesy Martin Deakins, GE Superabrasives, Worthington, OH. Used with permission.


32

Application: Sensors

- Example: Oxygen sensor ZrO_2
- Principle: Make diffusion of ions fast for rapid response.
- Approach:
 - Add Ca impurity to ZrO_2 :
 - increases O^{2-} vacancies
 - increases O^{2-} diffusion rate
- Operation:
 - voltage difference produced when O^{2-} ions diffuse from the external surface of the sensor to the reference gas.



A Ca^{2+} impurity removes a Zr^{4+} and a O^{2-} ion.



gas with an unknown, higher oxygen content

reference gas at fixed oxygen content

O_2 diffusion

voltage difference produced!

33

Applications: Advanced Ceramics

Heat Engines

- **Advantages:**
 - Run at higher temperature
 - Excellent wear & corrosion resistance
 - Low frictional losses
 - Ability to operate without a cooling system
 - Low density
- **Disadvantages:**
 - Brittle
 - Too easy to have voids weaken the engine
 - Difficult to machine
- **Possible parts – engine block, piston coatings, jet engines**
 - Ex: Si_3N_4 , SiC , & ZrO_2

34



Applications: Advanced Ceramics

- **Ceramic Armor**

Al_2O_3 , B_4C , SiC & TiB_2

Extremely hard materials

shatter the incoming projectile

energy absorbent material underneath

35



Applications: Advanced Ceramics

Electronic Packaging

- Chosen to securely hold microelectronics & provide heat transfer
- Must match the thermal expansion coefficient of the microelectronic chip & the electronic packaging material. Additional requirements include:
 - good heat transfer coefficient
 - poor electrical conductivity
- Materials currently used include:
 - Boron nitride (BN)
 - Silicon Carbide (SiC)
 - Aluminum nitride (AlN)
 - thermal conductivity 10x that for Alumina
 - good expansion match with Si

36



Summary

- Room T mechanical response is elastic, but fracture is brittle, with negligible deformation.
- Elevated T creep properties are generally superior to those of metals (and polymers).
- **Fabrication Techniques:**
 - glass forming (impurities affect forming temp).
 - particulate forming (needed if ductility is limited)
 - cementation (large volume, room T process)
- **Heat treating:** Used to alleviate residual stress from cooling, produce fracture resistant components by putting surface into compression.